



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB284

Issue Date: 11-7-2008

Description:

New Factory Burn-in Process for Hakko HJ5000 Heat Gun

Applies To:

HJ5000; HJ5000/P; HJ5000-RC-B; HJ5000-RC-G;
HJ5000-RC-O; HJ5000-RC-R

Specification:

Unchanged

Comments:

During the manufacturing process, residues are left on the heating element assembly which can cause light smoke and/or odor for the first few minutes of operation of a new heat gun. Due to customer concerns over the visible smoke, all HJ5000 heat guns are now burned in at the factory to burn off the manufacturing residue on the heating element assembly.

Available:

From HJ5000 shipments September 22, 2008 forward



From...

For additional information:

- End-User Customers – Call Customer Support at 1-800-88-HAKKO (42556)
- Authorized Distributors – Call Distributor Support at 661-294-0090

American Hakko Products, Inc.
28920 Avenue Williams.
Valencia, CA 91355
Tel: (661) 294-0090
Fax: (661) 294-0096
www.HakkoUSA.com
AHP14 Rev 2007-12