



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB360

Issue Date: 4-27-2015

Effective: 5-1-2015

Product Description:

HAKKO FR-810 Hot Air Rework Station

Part No:

FR810-05

Contents:

Unchanged

Specification:

Unchanged

Comments:

During the replacement of the heating element (PN: A5006) in the handpiece of the HAKKO FR-810 Hot Air Rework Station, the ceramic insulating fiber that surrounds the heater can be easily damaged, and old insulating fiber can remain unknowingly in the heater pipe.

To simplify the replacement of the heating element, the ceramic insulating fiber has been replaced with a ceramic sleeve which is easier to inset and remove during service.

As a result of this change, the contents and appearance of certain replacement parts for this unit has changed (Reference Product Bulletin PB361).

All shipments of the HAKKO FR-810 Hot Air Rework Station on or after May 1, 2015, or with serial number 07810215000054 or higher, will include the new ceramic sleeve in place of the ceramic insulating fiber.

For more information please visit us at www.HakkoUSA.com

