

American Hakko Products, Inc.



Bulletin No: PB377

*Issue Date:* 5-5-2016

*Available:* 5-5-2016

**Product Description:** Replacement Heater Pipe for HAKKO FR-810

**Part No:** B5045

## Specification:

Removed one of the two bosses



Previous Specification	New Specification
	Removed
	No Change

## Comments:

The HAKKO B5045 pipe for the HAKKO FR-810 hot air rework stations has changed to accommodate older generations of nozzles. The new pipe will work with the HAKKO N51 nozzles made for the HAKKO FR-810 and will no longer require the B5058 adaptor for nozzles from the HAKKO FR-801, FR-802, and FR-803B hot air units.

For more information please visit us at www.HakkoUSA.com

AHP14 Rev 2012-11