



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB444
Issue Date: 12-10-2019
Effective Date: 12-10-2019

Description/Title:
Discontinuation of the HAKKO FR-1418 SMD Rework System

Part No:
FR1418-xx

Specification:
DISCONTINUED

Comments:
The HAKKO FR-1418 SMD Rework System has been discontinued effective immediately.

The discontinued system will be replaced by the NEW HAKKO HJ4000-SET SMD Rework System. Please reference Product Bulletin PB445.

For more information, please visit www.HakkoUSA.com, e-mail Support@HakkoUSA.com, or call 1-800-88-HAKKO (42556).

