



American Hakko Products, Inc.

P R O D U C T B U L L E T I N

Bulletin No: PB230

Issue Date: December 5, 2005

Product: 852 SMD Rework Station

Part No: 852-3

Specification:

DISCONTINUED



Comments:

The Hakko 852 SMD Rework Station has been discontinued. The direct replacement for this unit is the new Hakko FR-803 SMD Rework Station (please see Product Bulletin No. PB233).

Discontinued on:

December 5, 2005

For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

From...

American Hakko Products, Inc.
28920 N. Avenue Williams.
Valencia, CA 91355
Tel: (661) 294-0090
Fax: (661) 294-0096
www.hakkousa.com
AHP14 Rev 2000-01