



American Hakko Products, Inc.

P R O D U C T B U L L E T I N

Bulletin No: PB258

Issue Date: September 5, 2007

Product:

T15 tip series for the FM-202 and FP-102 stations

Part No:

See attached list

Comments:

T15 series tips will replace the T7 series tip for the FM-202 and FP-102 stations. We are in the process of phasing out the barcode from the tips.

In almost every case determining the new T15 tip part number will be as simple as replacing the prefix T7 with T15. In a few cases the entire part number has changed. See the attached chart for a list of all the T15 part numbers with the corresponding T7 part number.

Due to the large number of T7 tips the change from T7 to T15 part numbers will be gradual. Contact American Hakko Products Customer Service at 1-800- 88 HAKKO (4-2556) for information on the current T15 series tips.

When T7 inventory is depleted the individual T7 part number will be discontinued and the tip will be replaced with the equivalent T15 tip.

Available:

Beginning August 30, 2007

For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

From...

American Hakko Products, Inc.
28920 N. Avenue Williams.
Valencia, CA 91355
Tel: (661) 294-0090
Fax: (661) 294-0096
www.hakkousa.com
AHP14 Rev 2000-01

T7 to T15 Cross reference

T15 part numbers with pink shade are the same tip shape as the listed T7 tip but with a different part number suffix.				
T7-B	T15-B		T7-R20	T15-R20
T7-BCF1	T15-BCF1		T7-R23	T15-R23
T7-BCF2	T15-BCF2		T7-R27	T15-R27
T7-BCF3	T15-BCF3		T7-R34	T15-R34
T7-BC1	T15-BC1		T7-R48	T15-R48
T7-BC12	T15-BC12		T7-SBC04	T15-SBC04
T7-BC15	T15-BC15		T7-SBS04	T15-SBS04
T7-BC2	T15-BC2		T7-SBS07	T15-SBS07
T7-BC28	T15-BC28		T7-SB02	T15-SB02
T7-BC3	T15-BC3		T7-SB03	T15-SB03
T7-B2	T15-B2		T7-SB05	T15-SB05
T7-B3	T15-B3		T7-SB08	T15-SB08
T7-B4	T15-B4		T7-SLI	T15-ILS
T7-CF2	T15-CF2		T7-XD15	T15-XD15
T7-CF3	T15-CF3		T7-1001	T15-1001
T7-CF4	T15-CF4		T7-1002	T15-1002
T7-C1	T15-C1		T7-1003	T15-1003
T7-C4	T15-C4		T7-1004	T15-1004
T7-D08	T15-D08		T7-1005	T15-1005
T7-D12	T15-D12		T7-1006	T15-1006
T7-D16	T15-D16		T7-1007	T15-1007
T7-D2	T15-D2		T7-1008	T15-1008
T7-D24	T15-D24		T7-1009	T15-1009
T7-D32	T15-D32		T7-1010	T15-1010
T7-D4	T15-D4		T7-1201	T15-1201
T7-D52	T15-D52		T7-1202	T15-1202
T7-I	T15-I		T7-1203	T15-1203
T7-JD14	T15-JD14		T7-1204	T15-1204
T7-JD16	T15-JD16		T7-1205	T15-1205
T7-JL02	T15-JL02		T7-1206	T15-1206
T7-JS02	T15-JS02		T7-1207	T15-1207
T7-J02	T15-J02		T7-1208	T15-1208
T7-K	T15-K		T7-1209	T15-1209
T7-KF	T15-KF		T7-1210	T15-1210
T7-KL	T15-KL		T7-1401	T15-1402
T7-KU	T15-KU		T7-1402	T15-1401
T7-LB	T15-BL		T7-1403	T15-1403
T7-LD4	T15-DL4		T7-1404	T15-1406
T7-LD52	T15-DL52		T7-1603	T15-1603
T7-LI	T15-IL		T7-1605	T15-1605
T7-LLB	T15-BLL		T7-1608	T15-1608

From...

For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

American Hakko Products, Inc.
 28920 N. Avenue Williams.
 Valencia, CA 91355
 Tel: (661) 294-0090
 Fax: (661) 294-0096
 www.hakkousa.com
 AHP14 Rev 2000-01