



American Hakko Products, Inc.

PRODUCT BULLETIN

Bulletin No: PB306

Issue Date: 2-4-2011

Effective Date: 2-4-2011

Product Description:

Hakko 928 Dual Port Soldering Station

Part No:


928xxx-VxxESD; 928-2E-V12ESD

Specification:

DISCONTINUED

Comments:

The Hakko 928 Dual Port Soldering Station has been discontinued. The Hakko FM-203 Soldering Station is the recommended replacement. Replacement parts for the Hakko 928 Dual Port Soldering Station will still be available only until the present parts supply is exhausted.



For more information, please visit our web site at www.HakkoUSA.com.

For additional information:

- End-User Customers – Call Customer Support at 1-800-88-HAKKO (42556)
- Authorized Distributors – Call Distributor Support at 661-294-0090

From...

American Hakko Products, Inc.
28920 Avenue Williams.
Valencia, CA 91355
Tel: (661) 294-0090
Fax: (661) 294-0096
www.HakkoUSA.com
AHP14 Rev 2007-12