



American Hakko Products, Inc.

# PRODUCT BULLETIN

**Bulletin No:** PB294

**Issue Date:** 2-3-2010

**Available:** February 2010

**Product Description:**

373 Solder Feeder Assembly for the Hakko FM-2027 Connector

**Part No:**

Various – See Specifications below.



**Specification:**

Solder Ø	Tube Unit	Guide Pipe Assy.
0.6/0.65mm	B3477	B3481
0.8mm		B3482
1.0mm		B3483
1.2mm	B3478	B3484
1.6mm	--	--

**NOTE:** 1.6mm Ø is NOT available for use.

**Comments:**

These new tube units for the 373 Solder Feeder are now compatible with the FM-2021 and FM-2027 Connectors. The larger 1.6mm diameter solder cannot be used due to the rigidity of the solder at that diameter.



Tube Unit (B3478 Pictured)



Guide Pipe Assembly (B3484 Pictured)

For more information on the Hakko 373 Solder Feeder and various assemblies to fit your Hakko soldering station, please visit our website at [www.HakkoUSA.com](http://www.HakkoUSA.com).

For additional information:

- End-User Customers – Call Customer Support at 1-800-88-HAKKO (42556)
- Authorized Distributors – Call Distributor Support at 661-294-0090

From...

American Hakko Products, Inc.  
28920 Avenue Williams.  
Valencia, CA 91355  
Tel: (661) 294-0090  
Fax: (661) 294-0096  
[www.HakkoUSA.com](http://www.HakkoUSA.com)  
AHP14 Rev 2007-12