



American Hakko Products, Inc.

# PRODUCT BULLETIN

**Bulletin No:** PB304

**Issue Date:** 1-18-2011

**Effective Date:** 1-18-2011

**Product Description:**

Hakko 937 Digital Soldering Station

**Part No:**

937-xx


**Specification:**

**DISCONTINUED**

**Comments:**

The Hakko 937 Digital Soldering Station has been discontinued. The Hakko FX-951 Soldering Station is the recommended replacement. Replacement parts for the Hakko 937 Digital Soldering Station will still be available only until the present parts supply is exhausted.

For more information, please visit our web site at [www.HakkoUSA.com](http://www.HakkoUSA.com).



From...

For additional information:

- End-User Customers – Call Customer Support at 1-800-88-HAKKO (42556)
- Authorized Distributors – Call Distributor Support at 661-294-0090

American Hakko Products, Inc.  
28920 Avenue Williams.  
Valencia, CA 91355  
Tel: (661) 294-0090  
Fax: (661) 294-0096  
[www.HakkoUSA.com](http://www.HakkoUSA.com)  
AHP14 Rev 2007-12