



American Hakko Products, Inc.

P R O D U C T B U L L E T I N

Bulletin No: PB241

Issue Date: June 1, 2006

Product:

903 Tips

Part No:

All 903 tips for the 939 station

Specification:

SPECIFICATION CHANGE

939 tips will no longer have an offset number written on the tip connector.

Comments:

The 939 Owner's Manual (page 10) describes the procedure for measuring and entering the tip offset.

Effective date:

June 1, 2006

For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

From...

American Hakko Products, Inc.
28920 N. Avenue Williams.
Valencia, CA 91355
Tel: (661) 294-0090
Fax: (661) 294-0096
www.hakkousa.com
AHP14 Rev 2000-01