



American Hakko Products, Inc.

P R O D U C T B U L L E T I N

Bulletin No: PB252

Issue Date: December 19, 2006

Product:

Sleeve Assembly for FM-2021 (FM-202/FP-102)

Part No:

B2765D

B2765D/P

B2768C

B2768C/P

B2769D

B2769D/P

B2996

Specification:

DISCONTINUED

Comments:

Sleeve assemblies for the FM-2021 connector assembly have been discontinued. The FM-2021 connector assembly for the FM-202 and FP-102 has been replaced by the FM-2027 locking connector assembly (see PB248 for details). Sleeve assemblies for the FM-2021 will not attach to the new FM-2027 connector assembly.

Effective:

December 18, 2006

For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

From...

American Hakko Products, Inc.
28920 N. Avenue Williams.
Valencia, CA 91355
Tel: (661) 294-0090
Fax: (661) 294-0096
www.hakkousa.com
AHP14 Rev 2000-01