



American Hakko Products, Inc.

P R O D U C T B U L L E T I N

Bulletin No: PB251

Issue Date: December 19, 2006

Product:

FP-102 Soldering Station

Part No:

FP102-01

Specification Change:

Add FM2027-02 locking connector assembly

Add B3216 (Sleeve assembly Yellow), B3217 (Sleeve assembly Orange), B3218 (Sleeve assembly Blue), or B3219 (Sleeve assembly Green)

Delete FM2021-02 connector assembly

Delete B2765D (Sleeve assembly Yellow), B2768C (Sleeve assembly Orange), or B2769D (Sleeve assembly Blue).

Comments:

The FP-102 Soldering Station now includes the FM-2027 locking connector assembly. See Product Bulletin PB248 for details of the FM-2027.

Available:

December 18, 2006

For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

From...

American Hakko Products, Inc.
28920 N. Avenue Williams.
Valencia, CA 91355
Tel: (661) 294-0090
Fax: (661) 294-0096
www.hakkousa.com
AHP14 Rev 2000-01