



**American Hakko Products, Inc.**

## P R O D U C T   B U L L E T I N

**Bulletin No:** PB206

**Issue Date:** November 1, 2004

**Product:**

Hakko 850B Hot Air Rework Station

**Part No:**

850B-3

**Specification:**

**DISCONTINUED**

**Comments:**

The Hakko 850B Hot Air Rework Station has been discontinued. The Hakko 850D Hot Air Rework Station (PN: 850D-01) and Hakko 852 Hot Air Rework Station (PN: 852-3) are alternate replacements for the Hakko 850B. Both units use closed-loop sensor control of the hot air temperature, eliminating the need to reference airflow/temperature setting charts for each nozzle used and giving you better control and stability of the rework temperature.

**Discontinued on:**

November 1, 2004

For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

From...

American Hakko Products, Inc.  
28920 N. Avenue Williams.  
Valencia, CA 91355  
Tel: (661) 294-0090  
Fax: (661) 294-0096  
[www.hakkousa.com](http://www.hakkousa.com)  
AHP14 Rev 2000-01